

## Skyzer Interface - Accredited 2 Way POS Systems

The following POS vendors have been certified to link directly with Ingenico terminals by Skyzer Technologies.

Terminals supported are as follows:

**ICT2xx, IWL252, MOVE5000, DESK5000, DESK3200 & MOVE2500. (MOVE2500 is Serial only.**

POS SYSTEM	NOTES
<b>ABEL POS</b>	ABLE POS system is not able to process Refund transaction as it is not supported by POS system.
<b>Accredo</b>	
<b>AniMarket</b>	AniMarket system is not able to process Refund and Cash out transaction as it is not supported by POS system.
<b>Apostle</b>	Apostle system is not able to process Refund transaction as it is not supported by POS system
<b>CASIO</b>	Casio ECR system requires to be updated with the latest IPL-EFP001 software for interfacing with ANZ terminals. TE2400   TE2200   QT6000 series   SES300   SES2000   SEC300   SEC2000   SEC6000   SES6000 VX-100   V-R100   V-R7100   SEC450
<b>Chreos</b>	
<b>eSalon</b>	
<b>G-POS</b>	GPOS system is not able to process Cash out transaction as it is not supported by POS system.
<b>Ideal POS</b>	
<b>InTech POS</b>	Intech POS is not able to process settlement, shift total and Cash out only transaction
<b>NEW 4 U/Retail Restaurant Management System</b>	NEW 4 U POS system is not able to process Cash out only and Refund transaction as they are not supported by POS system.
<b>NCC WeighForward POS)</b>	NCC POS does not support refund on the EFTPOS terminal or cash out.
<b>Point-3 / Point Three</b>	Point Three/3 requires a POS software upgrade to version 12.11.28 for interfacing with Ingenico.
<b>POS4US</b>	
<b>Posnet</b>	
<b>Professional System Limited</b>	
<b>ProTouch</b>	
<b>Prowzer</b>	Prowzer system is not able to process Cash out and Refund transactions as they are not supported by POS system.
<b>Quorion</b>	
<b>Sam4s (Samsung)</b>	<b>SAM4s ER-230/ER-265,230BEJ system is not able to process Cash out transaction as it's not supported by POS</b> ER-230   ER-390M   ER-380M   ER-420M   ER-600 ER-5200M   ER-650   SPS530   SPS2000   SPS300

	ER-230   ER-900   SPT-3000   NR520   ER-265BEJ ER-230 BEJ   ER-430M
SAM4POS	
<b>SwiftPOS</b>	SwiftPOS can communicate as 1 way with Ingenico. Please contact Skyzer to get the setting details. SwiftPOS requires a POS software upgrade to version 5.14.296.27 for interfacing as 2 way with Ingenico.
<b>TOWA</b>	SX-690II   SX-590II
<b>XCR Ltd</b>	
<b>WFT (Way Forward Technologies)</b>	
<b>WinPOS (The 123 Mart)</b>	
<b>WinStore</b>	WinStore is not able to process Cash out transaction as it is not supported by POS system.
<b>WizBang (OneTap)</b>	WizBang requires a POS software upgrade to version 10.0.0.2 for interfacing with Ingenico.

<b>Skyzer Interface - Accredited <u>1Way POS Systems</u></b>	
<b>POS SYSTEM</b>	<b>NOTES</b>
<b>MYOB Retail Manager</b>	MYOB Retail Manager requires a POS setup to allow interface communication with Ingenico terminal. Please contact Skyzer Technologies find out what specific setup is required.
<b>NC POS</b>	NC POS system is not able to process Refund transaction as it is not supported by POS system.
<b>NCR T1000</b>	
<b>POS 2 GO</b>	
<b>Quest</b>	Quest (Versa Term and V-Touch) communicates as 1 way interface with Ingenico terminals.
<b>Quick POS</b>	Quick Books/POS and requires version 2007 and later for interfacing with Ingenico.
<b>Reckon</b>	Reckon requires version 2007 and later for interfacing with Ingenico.
<b>SwiftPOS</b>	
<b>WinPOS (The 123 Mart)</b>	

**NOTE:**

Functions that are not supported at the POS end can be performed from the Ingenico terminal.