

## Skyzer Interface - Accredited 2 Way POS Systems

The following POS vendors have been certified to link directly with Ingenico terminals by Skyzer Technologies.

Terminals supported are as follows:

**MOVE5000, DESK5000, DESK3200 & MOVE2500. (MOVE2500 is Serial only)**

POS SYSTEM	NOTES
ABEL POS	ABLE POS system is not able to process Refund transaction as it is not supported by POS system.
Accredo	
AniMarket	AniMarket system is not able to process Refund and Cash out transaction as it is not supported by POS system.
Apostle	Apostle system is not able to process Refund transaction as it is not supported by POS system
CASIO	Casio ECR system requires to be updated with the latest IPL-EFP001 software for interfacing with ANZ terminals. TE2400   TE2200   QT6000 series   SES300   SES2000   SEC300   SEC2000   SEC6000   SES6000 VX-100   V-R100   V-R7100   SEC450
Chreos	
eSalon	V4
G-POS	GPOS system is not able to process Cash out transaction as it is not supported by POS system.
Ideal POS	
InTech POS	Intech POS is not able to process settlement, shift total and Cash out only transaction
NEW 4 U/Retail Restaurant Management System	NEW 4 U POS system is not able to process Cash out only and Refund transaction as they are not supported by POS system.
NCC WeighForward POS)	NCC POS does not support refund on the EFTPOS terminal or cash out.
Order Meal	V1
Point-3 / Point Three	Point Three/3 requires a POS software upgrade to version 12.11.28 for interfacing with Ingenico.
POS4US	
Posnet	
Professional System Limited	
ProTouch	
Prowzer	Prowzer system is not able to process Cash out and Refund transactions as they are not supported by POS system.
Quorion	

<b>Sam4s (Samsung)</b>	<b>SAM4s ER-230/ER-265,230BEJ system is not able to process Cash out transaction as it's not supported by POS</b> ER-230   ER-390M   ER-380M   ER-420M   ER-600 ER-5200M   ER-650   SPS530   SPS2000   SPS300
	ER-230   ER-900   SPT-3000   NR520   ER-265BEJ ER-230 BEJ   ER-430M
<b>SAM4POS</b>	
<b>SwiftPOS</b>	<b>SwiftPOS can communicate as 1 way with Ingenico. Please contact Skyzer to get the setting details.</b> <b>SwiftPOS requires a POS software upgrade to version 5.14.296.27 for interfacing as 2 way with Ingenico.</b>
<b>TOWA</b>	<b>SX-690II   SX-590II</b>
<b>XCR Ltd</b>	
<b>WFT (Way Forward Technologies)</b>	
<b>WinPOS (The 123 Mart)</b>	
<b>WinStore</b>	<b>WinStore is not able to process Cash out transaction as it is not supported by POS system.</b>
<b>WizBang (OneTap)</b>	<b>WizBang requires a POS software upgrade to version 10.0.0.2 for interfacing with Ingenico.</b>

## **Skyzer Interface - Accredited 1Way POS Systems**

<b>POS SYSTEM</b>	<b>NOTES</b>
<b>MYOB Retail Manager</b>	MYOB Retail Manager requires a POS setup to allow interface communication with Ingenico terminal. Please contact Skyzer Technologies find out what specific setup is required.
<b>NC POS</b>	NC POS system is not able to process Refund transaction as it is not supported by POS system.
<b>NCR T1000</b>	
<b>POS 2 GO</b>	
<b>Quest</b>	Quest (Versa Term and V-Touch) communicates as 1 way interface with Ingenico terminals.
<b>Quick POS</b>	Quick Books/POS and requires version 2007 and later for interfacing with Ingenico.
<b>Reckon</b>	Reckon requires version 2007 and later for interfacing with Ingenico.
<b>SwiftPOS</b>	
<b>WinPOS (The 123 Mart)</b>	

### NOTE:

Functions that are not supported at the POS end can be performed from the Ingenico terminal.