

Bulletin No.:

Date:

Subject:

Hardware: Software:

Effective Date:

As you are aware, Skyzer has made changes to the IKR Update. The terminal will now print confirmation receipts as follows. Refer to 3/3 for PINPad

- 1 The IKR application is checking the validity of the certificates
- 2- The PINPad Certificate has just been renewed
- 3 The Certification has NOT been renewed. SWAP THE PINPAD OUT AND RETURN TO SKYZER



Renewal Successful

No Further action

required

PUDDING_TELIUM File Received: /SYSTEM/IKR LAUNCH.PAR [IKR-LAUNCH] Version=4.00

[LAUNCH_PARAMETERS] Launch_RandomShiftMax=60]

PUDDING_TELIUM File Received: /SYSTEM/IKR_LAUNCH.PAR [IKR-LAUNCH] Version=4.00

[LAUNCH_PARAMETERS] Launch_RandomShiftMax=60]

IKR MAINTENANCE 02.00 24/02/21 23:47 Check At Risk SOFT CONF.: 3_X018E MNG: 87.18 OS: 54.20 NNG: 87.18 US: 54.20 Loc.:AUS/SKYZER-NZ 1/3 TID:0000286123537556 1/3 SSL PROD: M40 PKI:3 1/3 Exp.:300927030003Z

1/3: Already Valid 2/3 TID:0000286123537556 2/3 BS PROD: M40 PKI:3 2/3 BSdate: 210224234743 2/3 Exp.:300927030018Z 2/3: Already Valid

3/3 TID:0000134171377359 3/3 PER1 PROD: P28 PKI:3 3/3 BSdate: 210225095743 3/3 Exp.:210414103228Z 3/3: At Risk

Config. At Risk

IKR MAINTENANCE 02.00 24/02/21 23:47 Check At Risk SOFT CONT: 3 X018E MNG: 87.18 05: 54.20 Loc.:AUS/SKYZER-NZ 1/3 TID:0000286123537556 1/3 SSL PROD: M40 PKI:3 1/3 FXP.:30092797198037 1/3 Exp.:300927030003Z 2/3 TID:0000286123537556 2/3 BS PROD: M40 PKT:3 2/3 BSdate: 210224234750 2/3 Exp.:300927030018Z 3/3 TID:0000134171377359 3/3 PER1 PROD: P28 PKI:3 3/3 BSdate: 210225095750 3/3 Exp.:210414103228Z

Config. At Risk Start Operation 1/3: Already Valid (TE) 2/3: Already Valid (TE) 3/3: Renewed 3/3 Exp.:310222220312Z

24/02/21 23:49 Operation OK

Self-Deletion



Previously Renewed No further action required

PUDDING_TELIUM File Received: /SYSTEM/IKR_LAUNCH.PAR [IKR-LAUNCH] Version=4.00

[LAUNCH_PARAMETERS] Launch_RandomShiftMax=60]

IKR MAINTENANCE 02.00 24/02/21 10:46 Check At Risk SOFT CONF: 3 X022C MNG: 87.18 05: 54.20 Loc::AUS/SKYZER-W2 1/3 TID:0000255826422347 1/3 SSL PROD: M46 PKI:3 1/3 Exp.:270422043207Z 1/3: Already Valid 2/3 TID:0000259826422347

2/3 BS PROD: M40 PKI:3 2/3 BS PROD: M40 PKI:3 2/3 BSdate: 210224104651 2/3 Exp.:270422043202Z 2/3: Already Valid

3/3 TID:0000234920204747 3/3 PER1 PROD: PP3 PKI:3 3/3 BSdate: 191125104651 3/3 Exp.:3102212143102 3/3: Alpeady Valid

Config. Valid

Self-Deletion



ERROR! Not Renewed

PUDDING TELIUM File Received: /SYSTEM/IKR_LAUNCH.PAR [IKR-LAUNCH] Version=4.00

[LAUNCH_PARAMETERS] Launch_RandomShiftMax=60]

PUDDING_TELIUM File Received: /SYSTEM/IKR_LAUNCH.PAR [IKR-LAUNCH] Version=4.00

[LAUNCH_PARAMETERS] Launch_RandomShiftMax=60]

IKR MAINTENANCE 02.00 24/02/21 11:01 Check At Risk SOFT CONT: 3 X022C MNG: 87.18 OS: 54.20 Loc.:AUS/SKYZER-NZ 1/3 TID:0000259826422347 1/3 SSL PROD: M40 PKI:3 1/3 Exp.:270422043207Z 1/3: Already Valid

2/3 TID:0000259826422347 2/3 BS PROD: M40 PKI:3 2/3 BSdate: 210224110111 2/3 Exp.:270422043202Z 2/3: Already Valid 3/3 TID:0000234920683525 3/3 PER1 PROD: PP3 PKI:3 3/3 BSdate: 180612094346

3/3 Exp.:210414103637Z 3/3: At Risk

Config. At Risk

TKR MAINTENANCE 02.00 24/02/21 11:01 Check At Risk CHECK AC KLSK SOFT COMF.: 3_X022C MNG: 87.18 OS: 54.20 Loc.:AUS/SKYZER-NZ 1/3 TID:0000259826422347 1/3 SSL PROD: M40 PKI:3 1/3 Exp.:270422043207Z 2/3 TTD:0000259826422347

2/3 FID:000025982642234/ 2/3 BS PROD: M40 PKI:3 2/3 BSdate: 210224110119 2/3 Exp.:270422043202Z 3/3 TID:0000234920683525 3/3 PER1 PROD: PP3 PKI:3 3/3 BSdate: 180612094354 3/3 Exp.:210414103637Z

Config. At Risk Start Operation 1/3: Already Valid (TE) 2/3: Already Valid (TE)

3/3: KO 3/3 Exp.:210414103637Z

24/02/21 11:03 Abort:Keygen too long Self-Deletion